

HID® FARGO® DTC™ii Plus

Printer Firmware

Release Notes

Firmware Version: 3.4.9.1
PLT-05835, A.5
November 2024



Copyright

© 2021 - 2024 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, FARGO, and DTC are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
November 2024	Release notes for firmware release 3.4.9.1.	A.5

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the HID® FARGO® DTC™ii Plus Printer Firmware version 3.4.9.1. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from a HID Global internal tracking system

1.2 New features and enhancements

- Added the ability to not apply overlay on cards printed by the DTCii Plus. (FSA-399)
- Added the ability to load certifications from CA to printer. (FSA-1044)

Note: Tech support documentation will be created and added to the TRISM Document Library at:
https://www.hidglobal.com/documents?search_key=trism

1.3 Resolved issues

- Added CSP (Content Security Policy) header to WebApp responses. (SIFI-2586)
- Removed unintended text on button showing in the Diagnostics Webpage. (SIFI-1086)
- Updated SSL Certificates. (FSA-1085)
- Updated support for generation of v3 certificates in Device Maintenance. (SIFI-2592)

1.4 Firmware upgrades

Important: Firmware upgrades must be sequential. For example, a printer with firmware Rev F has to update to firmware Revision G (Parts I & II) before upgrading to this firmware revision H release
FRW-02095_RevH_FW_UPGRADE_BUNDLE_DTICIPLUS_ON_PREMISE_v3.4.9.1.frm

Install FRW-02095_RevH_FW_UPGRADE_BUNDLE_DTICIPLUS_ON_PREMISE_v3.4.9.1.frm. This bundle contains new web services and printer firmware version 3.2.0.651. Installation time is approximately two minutes.

1.5 Known issues

- A power outage during a firmware upgrade may result in the printer not starting up successfully. (DTICIPLUS-349)
- The MAC address on the Network Settings test card is incorrect (though it is correct on the Printer Settings test card). (HVT5-548)

Revision history

Date	Description	Revision
November 2024	Release notes for firmware release 3.4.9.1.	A.5
February 2024	Release notes for firmware release 3.4.9.1	A.4
February 2023	Release notes for firmware release 3.3.1.1.	A.3
May 2022	Release notes for firmware release 3.0.6.1.	A.2
April 2021	Release notes for firmware release 2.1.7.1.	A.1
April 2021	Release notes for firmware release 2.1.5.1.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2024 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-05835, Rev. A.5

Part of ASSA ABLOY