

HID® FARGO® DTC™4500 / DTC4500e

Laminator Firmware

Release Notes

Firmware Version: 1.3.5.1
PLT-04852, A.2
July 2024



Copyright

© 2021 - 2024 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, FARGO, and DTC are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
July 2024	Release notes for firmware release 1.3.5.1.	A.2

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the HID® FARGO® DTC™4500 / DTC4500e Laminator Firmware version 1.3.5.1. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from a HID Global internal tracking systems.

1.2 Upgrade information

For FARGO Workbench version 3 or higher:

1. Run the FARGO Workbench Printer Utility.
2. Choose the **Update Manager** Workbench Utility.
3. Select the printer you wish to update.
4. Click **Select Firmware file** to locate or enter this firmware file
D930359_RevK_DTC4500.LAM_v1.3.5.1.frm
5. Search for the firmware file or enter its name, then click **Open**.
6. Click **Begin Updating Firmware** to send the file to the printer.

For older versions of FARGO Workbench:

1. Run the FARGO Workbench Printer Utility.
2. From the Application menu, select **Upgrade Firmware**.
3. Enter the firmware file name or click **Browse** to find and select this firmware file
D930359_RevK_DTC4500.LAM_v1.3.5.1.frm
4. Click **OK** to send the file to the printer.

Note: It will take approximately five minutes to upgrade the firmware and complete the process.

1.3 Resolved issue

- Resolved an issue with card jams while ejecting by reducing the default eject speed. (HVPB-564, TTP-14564)

Note: This change was implemented into production in February 2022 (DEV-05789) and is now implemented in the firmware.



Revision history

Date	Description	Revision
July 2024	Release notes for firmware release 1.3.5.1.	A.2
February 2021	Release notes for firmware release 1.2.81.0.	A.1
January 2020	Initial release.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2024 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-04852, Rev. A.2

Part of ASSA ABLOY