

HID® FARGO® DTC™4250e

Printer Firmware
Release Notes

Firmware Version: 3.7.0.8
PLT-06708, Rev. A.4
February 2026



Copyright

© 2022 - 2026 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, DTC, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
February 2026	Release notes for version 3.7.0.8.	A.4

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the HID® FARGO® DTC™4250e Printer Firmware version 3.7.0.8. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from the HID Global internal tracking system.

1.2 New features

- Added web page enable/disable to LCD menu. (FSA2-2410)
- Added enhancements to comply with European Radio Equipment Directive - Delegated Act (RED-DA). (FSA-1408)
- Updated job encryption to be compliant with RED-DA. This requires an updated driver version (5.6.x or above).
- Added support for NextGen ribbon. (FSA-1396)

Important: If using Next Generation ribbons, please update your driver, firmware, and color profile to ensure best results. Visit <https://player.vimeo.com/video/1111075180> for step-by-step instructions.

1.3 Resolved issues

- Resolved an issue with job data error, after sending rewritable print jobs. (FSA2-2564)
- Resolved an issue with a random Ribbon RFID Error and Ribbon Miscue (error 97) after upgrading to FW 3.3.20.1 (TTP-16000, FSA-1107)
- Resolved or improved an issue with using a YMCKOKO split panel ribbon that was generating error 100. (TTP-15868, FSA-987)

Revision history

Date	Description	Revision
February 2026	Release notes for version 3.7.0.8.	A.4
February 2025	Release notes for version 3.3.23.2.	A.3
December 2023	Release notes for version 3.3.20.1.	A.2
November 2023	Release notes for version 3.3.19.1.	A.1
December 2022	Release notes for version 3.3.10.1.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2026 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-06708, Rev. A.4

Part of ASSA ABLOY