

HID® FARGO® HDP®6600

Printer Firmware

Release Notes

Firmware Version: 10.0.46.592
PLT-04251, B.1
June 2025



Copyright

© 2019 - 2025 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, FARGO, FARGO Connect, and HDP are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
June 2025	Release notes for firmware version 10.0.46.592.	B.1

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID® FARGO® HDP®6600 version 10.0.46.592. Included are product features, enhancements, and resolved issues since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

1.2 New feature

- Added **Transfer TOF Offset – Reverse Side** setting. This allows you to change the **Transfer TOF** on the back side of the card without affecting the front side TOF. (FSA2-1704, FSA-1147)

Note: If this setting, **Transfer TOF Offset - Reverse Side** is needed, you can adjust this setting by changing the current default value by -1. For example, change the setting from 0 to -1, then to -2, and so on. Increment by one step at a time until the white gap is gone. Typically a setting in the range of -1 to -10 fixes most printers.



1.3 Resolved issues

- Resolved an issue, when printing and pausing resin scramble, a cover open would lock up the printer. (FSA2-1560)
- Resolved an issue where after a printer went to sleep mode the user opened the door briefly to attempt to use the LCD buttons to move the card path left or right. (FSA2-1760)
- Added support for **Blush Point** in the printer firmware. (TTP-14382, FSA-547)

1.4 Known issues

- While using **Resin Scramble**, the printer can sometimes continue a print job with the front cover open. (FSA2-1899)
- When using HID® FARGO® Connect™ it may report error **454 Waiting for Data**. (TTP-13763)

Revision history

Date	Description	Revision
June 2025	Release notes for firmware version 10.0.46.592.	B.1
March 2024	Release notes for firmware version 10.0.37.524.	B.0
March 2023	Release notes for firmware version 10.0.25.431.	A.9
February 2022	Release notes for firmware version 9.0.36.352.	A.8
October 2020	Release notes for firmware version 6.0.12.6020.	A.7
July 2020	Release notes for firmware version 6.0.12.6014.	A.6
July 2020	Release notes for firmware version 6.0.9.6011.	A.5
April 2020	Release notes for firmware version 6.0.9.6011.	A.4
January 2020	Release notes for firmware release 5.0.5.1084.	A.3
July 2019	Release notes for firmware release 3.0.8.1063.	A.2
July 2019	Release notes for firmware release 3.0.7.1056.	A.1
April 2019	Release notes for firmware release 2.0.32.952.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2025 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-04251, Rev. B.1

Part of ASSA ABLOY