

HID® FARGO® DTC™5500LMX

Laminator Firmware Release Notes

Firmware Version: 1.1.2.1
PLT-06936, A.0
February 2023



Copyright

© 2023 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, FARGO, and DTC are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
February 2023	Release notes for 1.1.2.1.	A.0

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the HID® FARGO® DTC™5500LMX Laminator Firmware version 1.1.2.1. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from the HID Global internal tracking system.

1.2 Resolved issue

Resolved an issue where the rotator motor stalls and causes card jams. (TTP-14123)

Revision history

Date	Description	Revision
February 2023	Release notes for 1.1.2.1.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2023 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-06936, Rev. A.0

Part of ASSA ABLOY