

HID® FARGO® INK1000

Printer Firmware

Release Notes

Version: 2.0.1
PLT-05365, A.2
August 2021



Copyright

© 2021 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
August 2021	Release notes to support firmware version 2.0.1.	A.2

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the HID® FARGO® INK1000 Printer Firmware version 2.0.1. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: This version of the INK1000 printer firmware requires version 2.0.0.0 or greater of the INK1000 printer driver. The latest version of this printer driver can be downloaded from [HID Drivers & Downloads](#).

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

1.2 New features and enhancements

- A print mode of Normal has now been added. The print quality associated with this print mode falls between the other print modes (Fast and Premium). (EINSTEIN-292)
- A Dark Background Image option has been added which should improve the print quality if a background being printed on the card is dark. (EINSTEIN-323)

1.3 Resolved issues

While printing, the ink cartridge could sometimes engage the capping station which had both a noise effect and could effect print quality.

Revision history

Date	Description	Revision
August 2021	Release notes to support firmware version 2.0.1.	A.2
November 2020	Release notes to support firmware version 1.1.12.	A.1
September 2020	Initial release.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2021 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-05365, Rev. A.2

Part of ASSA ABLOY