

FARGO® DTCii Windows Printer Driver

Release Notes

PLT-04546, A.1
September 2022



Copyright

© 2019 - 2022 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, DTC, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
September 2022	Release notes for driver version 5.4.0.1	A.1

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the FARGO® DTC®ii Windows printer driver version 5.4.0.1. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

1.2 Supported operating systems

- Windows 7 x86/x64
- Windows 10 x86/x64
- Windows 11 (x64)
- Windows Server 2012 R2
- Windows Server 2016
- Windows Server 2019
- Windows Server 2022

1.3 Resolved issues

Resolved an occasional issue with Windows 10 (1903). When updating the driver, it no longer prompts users to stop the spooler service. (TTP-11917, SCSEP-77)

Revision history

Date	Description	Revision
September 2022	Release notes for driver version 5.4.0.1	A.1
September 2019	Release notes for driver version 5.4.0.1	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2022 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-04546, Rev. A.1

Part of ASSA ABLOY