

HID® FARGO® HDP®5600

Printer Firmware

Release Notes

Firmware Version: 6.9.1
PLT-04725, A.2
April 2023



Copyright

© 2019 - 2023 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, FARGO, and HDP are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
April 2023	Release Notes for firmware version 6.9.1.	A.2

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID FARGO® HDP®5600 Printer Firmware version 6.9.1. Included are product features, enhancements, and resolved issues since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

1.2 Resolved issue

- Resolved a card transfer speed issue from printer to lamination module that occasionally caused old rollers to generate black debris/specks that are visible after the card is printed/laminated. (TTP-12702)

1.3 Known issues

- Performing firmware upgrades using FARGO Workbench on Windows 10 when not running as an administrator may result in errors. (SICPI-605)
- If the printer cover is opened when the printer is in the **Paused** state, the printer may not resume printing correctly. (SICPI-606)
- KI ribbon is not supported.

Revision history

Date	Description	Revision
April 2023	Release Notes for firmware version 6.9.1.	A.2
October 2020	Release Notes for firmware version 6.9.0.	A.1
February 2019	Release Notes for firmware version 6.8.4.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2023 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-04725, Rev. A.2

Part of ASSA ABLOY