

HID® Reader Manager™ App (iOS)

Release Notes

App Release 1.32.0
PLT-03808, Rev. F.6
December 2025



Copyright

© 2019 - 2025 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, HID Reader Manager, HID Signo, Seos, HID iCLASS, HID iCLASS SE, and HID multiCLASS SE are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
December 2025	Updated Release Notes to support HID Reader Manager 1.32.0	F.6

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on HID® Reader Manager™ App 1.32.0 (iOS). Included are new product features and enhancements, resolved issues, and known issues since the previous release.

1.2 New features and enhancements

HID Reader Manager App 1.32.0 (iOS) includes enhancements and resolves the following issues:

- **Reader Friendly Name:** added the ability for Reader Technicians to edit the HID Signo reader's default name (UUID) and give it a friendly name.
- **SP 11 support:** added the ability for Reader Technicians to upgrade HID Signo readers from any supported firmware version to version 10.0.11.5 using the HID Reader Manager app.
- **HID Signo Factory Feature Block No BLE and No LF reader support:** added the ability to disable LF and BLE configuration parameters for HID Signo Factory Feature Block No BLE and No LF readers.
- **Technology update:** integrated the Mobile Event Logger for iOS, enabling future migration from Mix panel.

We are continuously improving our app to provide you with the best possible experience. Thank you for your feedback and support. Update now to enjoy these enhancements.

1.3 Limitations

- The keys selected for Mobile Admin, Mobile Access, Apple Wallet, and Google Wallet are overwritten when a Reader Technician loads any key to a reader via **Credential details > Key** in the Inspection Report. It is recommended to reconfigure the reader by selecting the required keys for Mobile Admin, Mobile Access and Wallet via the mix and match UI flow.
- HID Signo reader firmware version 10.0.9.1 has limitations with OSDP V1 settings. Changing the reader configuration to OSDP V1 via HID Reader Manager is not currently supported.
- Upgrading iCLASS and multiCLASS SE readers to the latest R8.10.2.7 firmware prevents the reader from accepting current reader configuration card part numbers. A new configuration card part number is required to support R8.10.2.7.

Note: Add "-1" suffix to the existing part number to submit an order for a new configuration card part number. For example, "SEC9X-CRD-0-12345" becomes "SEC9X-CRD-0-12345-1". These are expected to be available to order in early November 2024. Please contact your local HID Technical Support representative for any queries relating to this issue.

- Only use NFC to apply OSDP (Communication Protocol) or Transact mobile (Credential) configurations after upgrading to either R8.9.3.6 or R8.10.2.7. The issue will be addressed in a future release of HID Reader Manager.

Revision history

Date	Description	Revision
December 2025	Updated Release Notes to support HID Reader Manager 1.32.0	F.6
October 2025	Updated Release Notes to support HID Reader Manager 1.31.0	F.5
June 2025	Release Notes to support HID Reader Manager 1.30.0	F.4
February 2025	Release Notes to support HID Reader Manager 1.24.1	F.3
January 2025	Release Notes to support HID Reader Manager 1.24.0	F.2
November 2024	Release Notes to support HID Reader Manager 1.23.0	F.1
October 2024	Update to Release Notes to support HID Reader Manager 1.22.0	F.0
September 2024	Release Notes to support HID Reader Manager 1.22.0	E.9
July 2024	Release Notes to support HID Reader Manager 1.21.0	E.8
June 2024	Release Notes to support HID Reader Manager 1.20.0	E.7
March 2024	Release Notes to support HID Reader Manager 1.19.0	E.6
January 2024	Release Notes to support HID Reader Manager 1.18.0	E.5
November 2023	Release Notes to support HID Reader Manager 1.17.2	E.4
October 2023	Release Notes to support HID Reader Manager 1.17.1	E.3
September 2023	Release Notes to support HID Reader Manager 1.17.0	E.2
August 2023	Release Notes to support HID Reader Manager 1.16.1	E.1



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2025 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-03808, Rev. F.6

Part of ASSA ABLOY