

HID® FARGO® DTC™5500LMX

Firmware

Release Notes

Firmware Version: 1.2.10.1
PLT-06251, A.2
January 2025



Copyright

© 2021 - 2025 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, DTC, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
January 2025	Release notes for 1.2.10.1.	A.2

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID® FARGO® DTC™5500LMX Firmware version 1.2.10.1. Included are product features, enhancements, and resolved issues since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

This firmware update includes the printer only. The file name is: FRW-00728_RevL_DTC5500LMX_v1.2.10.1.frm.

1.2 Resolved issues

- Resolved an issue where the Utility command requested the number of cards remaining before cleaning is required. (FSA-618)
- Resolved an issue where an unnecessary beep was audible when the printer driver read the printer internal settings. (FSA5-897)

1.3 Known issue

- Occasionally cards push back on the input hopper. (TTP-15206, FSA-791)

Revision history

Date	Description	Revision
January 2025	Release notes for 1.2.10.1.	A.2
April 2023	Release notes for 1.2.9.1	A.1
October 2021	Release notes for 1.2.7.4.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2025 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-06251, Rev. A.2

Part of ASSA ABLOY