

HID® FARGO® DTC™5500LMX

Firmware Bundle

Release Notes

Firmware Bundle Version: 1.2.9.1
PLT-06251, A.1
April 2023



Copyright

© 2021 - 2023 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, DTC, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
April 2023	Release notes for 1.2.9.1.	A.1

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID® FARGO® DTC™5500LMX Firmware Bundle version 1.2.9.1. Included are product features, enhancements, and resolved issues since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

The bundle file name is: FRW-01229_RevQ_DTC5500LMX_v1.2.9.1.frm

This file is a bundle, for end users and production to update firmware in both the printer and the laminator at the same time, in a single download.

This firmware bundle (two files embedded as one) includes the following printer and laminator part number release versions:

- **Printer firmware:** FRW-00728_RevQ_DTC5500LMX_v1.2.9.1.frm
- **Laminator firmware:** FRW-00730_RevN_DTC5500LMX_v1.1.2.1.frm

1.2 New features and enhancements

The firmware has been updated to be compatible with the latest electrical components being used in the manufacturing of this printer model.

Note: The firmware is backwards compatible to printers that were previously manufactured.

The firmware bundle has been updated to include the latest laminator firmware. See *HID FARGO DTC5500LMX Laminator Firmware Release Notes* (PLT-06936) for the full list of resolved issues included in the laminator firmware.

Revision history

Date	Description	Revision
April 2023	Release notes for 1.2.9.1.	A.1
October 2021	Release notes for 1.2.7.4.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2023 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-06251, Rev. A.1

Part of ASSA ABLOY